


PURCHASE ORDER

(REQUIRED FOR ITEMS OVER \$500)



BILL TO :
CITY OF MILTON
710 S JANESVILLE ST
MILTON, WI 53563-1748
608-868-6900

P.O. NUMBER

P.O. DATE

VENDOR #

VENDOR:

CTW Corporation
21500 W. Good Hope Road
Lannon WI 53046-9720

1/15/16

CTW Corporation

TAX EXEMPT # 138244B
FEDERAL ID # 39-6006322

SHIP TO:
(If different
from Above)

City of Milton
150 Northside Dr
Milton WI 53563

G/L ACCOUNT #	QUANTITY	DESCRIPTION	UNIT PRICE	TOTAL PRICE
Water Capex 1	Expansion	Attached		\$ -
		Cost is between \$10-12,000	10-12000	\$ 10-12000 -
		Televising it needed \$875	875	\$ 875 -
		\$12875 Top cost		\$ -
				\$ -
				\$ -
				\$ -
Contractor that started the work last year for the 3rd 1/15 we have one per year.			TOTAL PURCHASE \$	\$ 12875 -

OFFICE USE

DEPARTMENT HEAD

CITY ACCOUNTANT

CITY ADMINISTRATOR

Date

Date

Date

CHECK ALL THAT APPLY:

☐ AT LEAST 3 QUOTES ATTACHED LOWEST SELECTED

☐ AT LEAST 3 QUOTES. LOWEST NOT SELECTED, REPORT
SUPPORTING RECOMMENDATION ATTACHED

☒ FEWER THAN 3 QUOTES - REPORT ATTACHED

☐ COUNCIL APPROVAL (IF OVER \$10,000) DATE: _____



CORPORATION
Water Wells & Pumps
www.ctwcorporation.com

October 8, 2015

MR RON GRIFFIN
CITY OF MILTON WATER
430 E HIGH ST STE #3
MILTON WI 53563

Subject: Well pump #6 Inspection

Dear Ron:


In recent years we have discussed the necessity to remove the pumping equipment from well #6 in order to evaluate its present condition since the original installation back in 2007. Knowing the history of how your other pumps hold up for normal 8-10 year intervals, the timing is right to plan for this work. Back in August of 2014 we sent an email where we suggested a budget figure of \$10,000-\$12,000 to remove the entire pump, evaluate the components, rebuild the bowl assembly to new specs, rebuild the stuffing box, replace the airline and rubber lineshaft bearings, disinfect the well and then install-flush-sample the rebuilt equipment. That cost estimate assumes that the column pipe and lineshaft will be in good shape and would be re-used with the rebuilt pump bowls and other items.

Since the time of that first proposal we have also discussed the benefits of performing a video inspection of the well while the pump is being repaired. That would allow for evaluating how clean the formation is and if any bacterial growth has begun to form in the water bearing sections of the well. While that service isn't absolutely necessary, it would allow you to address at an early stage anything that looks like it could lead to long term problems in the future. The added cost to televise would be \$875 but you can certainly wait to see what the removed pump components look like to aid in your decision on that.

This work could be conducted over the winter months when water use is low and would require that station to be out of service for about 10-14 days. We would recommend conducting both a performance test as well as collecting baseline vibration readings that can be duplicated once the pump is back in service. We hope we can be of service to you and the City in completing this work and ask that you call with any questions that you might have pertaining to our proposal. In the mean time, please let us know if anything else comes up that we can lend assistance to you or Lon over at the WWTP.

Beset Regards,

CTW CORPORATION


Timothy J. Cummins, PE